



S
sheeshmahal®



#S-001 A

WASHING INSTRUCTIONS
DO NOT USE ANY TYPE OF BLEACH OR STRONG BLEACHING CHEMICALS
BEFORE DYEING/STAINING/FABRIC SHOULD BE SOAKED IN WATER
ALL COMPONENTS SEPARATELY FOR 15 MINUTES
DO NOT KEEP HOT FABRIC IN TRAYED FROM IN ORDER TO AVOID CRIP MARKS
HIGH-COLOURED AND WHITE FABRICS SEPARATELY
IRON CLOTHES AT MODERATE TEMPERATURE DO NOT DRY FABRIC IN DIRECT SUNLIGHT
(EXTRA LACES/HANGINGS AND ACCESSORIES ARE NOT INCLUDED)



S
sheeshmahal®



#S-001 B

WASHING INSTRUCTIONS
DO NOT USE ANY TYPE OF BLEACH OR STRONG BLEACHING CHEMICALS
BEFORE DYEING OR COLORING SHOULD BE DONE IN COLD WATER
ALL COMPONENTS SHOULD BE WASHED SEPARATELY
DO NOT KEEP HOT FABRIC IN TRAYED FROM IN ORDER TO AVOID COLOR BLEEDING
WASH COLORED AND WHITE FABRICS SEPARATELY
IRON CLOTHES AT MODERATE TEMPERATURE DO NOT DRY FABRIC IN DIRECT SUNLIGHT
(EXTRA LACES/HANGINGS AND ACCESSORIES ARE NOT INCLUDED)



S
sheeshmahal®



#S-001 C

WASHING INSTRUCTIONS
DO NOT USE ANY TYPE OF BLEACH OR STRONG BLEACHING CHEMICALS
BEFORE DYEING/RE-DYEING SHOULD BE DONE IN COLD WATER
ALL COMPONENTS WASHED FOR 15 MINUTES
DO NOT USE HOT WATER. IN TRIMMED FROM IN ORDER TO AVOID CUP MARKS
HIGH-COLOURED AND WHITE FABRICS SEPARATELY
IRON CLOTHES AT MODERATE TEMPERATURE DO NOT DRY FABRIC IN DIRECT SUNLIGHT
(EXTRA LACES/HANGINGS AND ACCESSORIES ARE NOT INCLUDED)





S
sheeshmahal®



#S-001 A



#S-001 B



#S-00A C

